APPENDIX B

PHOTO LOG

Photo #1

Photographer: Tim Pool

Date: October 4, 2016

Description: Fueling station ASTs. Facing

east.



Photo #2

Photographer: Tim Pool

Date: October 4, 2016

Description: Storage building at fueling

station. Facing east.




Photo #3

Photographer: Tim Pool

Date: October 4, 2016

Description: AST fueling generator near

colorant area. Facing west.



Photo #4

Photographer: Tim Pool

Date: October 4, 2016

Description: Generator powering equipment at the colorant area. Facing east.



Photo #5

Photographer: Tim Pool

Date: October 4, 2016

Description: Recently watered ground to control dust in the colorant area. Facing

east.



Photo #6

Photographer: Tim Pool

Date: October 4, 2016

Description: New sedimentation pond at northwest corner of the Facility. Facing

south.



Photo #7

Photographer: Tim Pool

Date: October 4, 2016

Description: AST in wood grinding area north end of the Facility. Facing east.



Photo #8

Photographer: Tim Pool

Date: October 4, 2016

Description: Note fuel tank nozzle not stored properly and uncovered waste

receptacle. Facing north.



Photo #9

Photographer: Tim Pool

Date: October 4, 2016

Description: AST in wood grinding area.

Facing south.



Photo #10

Photographer: Tim Pool

Date: October 4, 2016

Description: View of wood storage, composting windrows and sedimentation

ditches. Facing south.



Photo #11

Photographer: Tim Pool

Date: October 4, 2016

Description: Pump for moving water out of sedimentation ditches. Note two outfall

signs. Facing west.



Photo #12

Photographer: Tim Pool

Date: October 4, 2016

Description: Damage filter socks at southwest corner of the Facility. Facing

north.



Photo #13

Photographer: Tim Pool

Date: October 4, 2016

Description: Waste oil AST and small containers of petroleum products at

lubrication station. Facing south.



Photo #14

Photographer: Tim Pool

Date: October 4, 2016

Description: Retail sales area. Facing

east.



Photo #15

Photographer: Tim Pool

Date: October 4, 2016

Description: Covered material area. Note water haul roads for dust control.

Facing north.

